



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Dennis Ware
OGM	Steve Demozak

Inspection Report

Permit Number:	C0070038
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, September 22, 2010
Start Date/Time:	9/22/2010 12:00:00 PM
End Date/Time:	9/22/2010 2:00:00 PM
Last Inspection:	Thursday, August 26, 2010

Inspector: Steve Demczak, Weather: Cloudy, rain, 60's

InspectionID Report Number: 2509

Accepted by: jhelfric

9/28/2010

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP
Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

14,662.49	Total Permitted	✓ Federal	✓ Underground			
71.44	Total Disturbed	☐ State	Surface			
125.41	Phase I	☐ County	✓ Loadout			
92.45	Phase II	✓ Fee	Processing			
92.45	Phase III	✓ Other	Reprocessing			
92.45	Phase III	✓ Other				

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division that the second quarter of 2010 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading.

The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2006.

There are no pending compliance actions.

There is currently no activity at this site.

Inspector's Signature:

Steph & Rengh Steve Bemczak,

Date

Monday, September 27, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, September 22, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	V		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		~	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		V	
13.	Revegetation	✓		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038
Inspection Type: PARTIAL

Inspection Date: Wednesday, September 22, 2010

Page 3 of 3

2. Signs and Markers

The identification signs is next to the road to the property. The information meets the R645 Coal Rules.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function during a storm event.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I did not see any hazardous conditions during the inspection. The pond contained a small amount of water.

4.c Hydrologic Balance: Other Sediment Control Measures

The reclaimed area is pocked for sediment control.

4.d Hydrologic Balance: Water Monitoring

Water monitoring was submitted to the Division for the second guarter of 2010.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile has been reclaimed. The premittee has received approval for longer having to conduct inspection on the refuse pile.

8. Noncoal Waste

The site is clear of non-coal waste material.

10. Slides and Other Damage

The site is clear of non-coal waste material.

12. Backfilling And Grading

The total disturbed area is reclaimed and is backfilled and graded.

13. Revegetation

The site has been seeded. Vegetation is growing on the site.

18. Support Facilities, Utility Installations

There are no facilities.